



By main entrance,
ideally needs repair





If someone wants to climb the wall,
it is easy and sadly with ledges, its easy to climb



What is the final plan
for this area ?



The palm trees bases
will need regular maintenance,
will the town hall commit to that ?



The palm trees bases
will need regular maintenance,
will the town hall commit to that ?



These images start at the left,
following wall along road side
from the main entrance.

So this is block 8, 172cm

So this is in front block 8, 162cm



So this is in front block 8, 170cm



This is in front block 8 & 7
path to pools, 150cm



This is start of block 7, 169cm



So this is in front block 7, 191cm





This is infront block 7, 215cm

This is infront block 7, 200cm





This is infront right side block 7, 182cm





This is in front block 6, 203cm



This is new wall, infront block 6
and pavement needs finishing



This is Infront block 6, 203cm



This is in front block 6, 227cm



This is in front right corner block 6, 205cm



This is in front block 6 & 5, 241cm



This is in front block 6 & 5, 270cm



This is in front block 5, 290cm



What is the plan for the top of the
planter wall and for the planter?
Council or LT?



What is the plan for the top of this
other planter wall and for the planter?
Council or LT?



This is in front forest, 287cm



This is in front forest, 180cm

This is in front forest, 130cm
but its a long way down other side





This is in front forest, 100cm
with estimated 250cm drop
other side